



Ph: (800) 253-6300
 Fax: (201) 337-6540
 sales@mulhernbelting.com
 www.mulhernbelting.com

How To Order SpeedSplice

Which Style of SpeedSplice do I need?

Part #	Description	PIW Strength	Material Thickness
Speed35MORCOS	MOR, Cover-One-Side	200	3/16" to 7/16"
Speed63MORCBS	MOR, Cover-Both Sides	360	3/16" to 5/8"
Speed63MORCOS	MOR, Cover-One-Side	360	3/16" to 5/8"
Speed63SBRCBS	SBR, Cover-Both-Sides	360	3/16" to 5/8"

The belt can be skived or unskived. Material Thickness is the thickness of the material the screw will pass through.

How much SpeedSplice do I need?

Belt Width	Length needed, installed on a bias 1" for every 12" of belt width
18"	20"
24"	26"
30"	33"
36"	39"
42"	46"
48"	52"
60"	65"
72"	78"
84"	91"

How long a screw do I need?

Material Thickness	Screw Length
1/8" to 5/32"	3/8"
5/32" to 7/32"	1/2"
7/32" to 5/16"	9/16"
5/16" to 3/8"	5/8"
3/8" to 31/64"	11/16"

The belt can be skived or unskived. Material Thickness is the thickness of the material the screw will pass through.

About how many screws will I receive?

Belt Width	# of Screws
18"	105
24"	140
30"	175
36"	210
42"	245
48"	280
60"	350
72"	420
84"	490

Approximately 70 screws per 12" of SpeedSplice will be provided.

[SpeedSplice
Installation
Instructions](#)

